



KING'S LYNN CONSERVANCY BOARD.

Notice to Mariners No.18/2024

East Coast of England - The Wash

Approaches to King's Lynn

Collapse of Beacon B

Mariners are advised that Beacon B (52° 49'.090N 000°21'.136E) has been severely damaged following collision by a fishing boat and is currently unlit.

The area to the West of above position is to be considered as foul ground.

Works to remove the beacon and establishment of a temporary buoy or beacon will be progressed and further NtMs will be issued as required.

Please contact the Harbour Office for further information.

22.07.24

P Jary
Harbour Master.
Harbour Office,
King's Lynn,
Norfolk PE30 ILL
www.kingslynnport.co.uk