



KING'S LYNN CONSERVANCY BOARD.

Notice to Mariners 4/ 2025.

East Coast of England - The Wash

Approaches to King's Lynn Harbour.

Number 23 Buoy - Navigational Mark – On Station.

BA 1200 Y9

Mariners are advised that Number 23 Buoy Navigational Mark damaged unit has been recovered and a replacement buoy is now on station.

No 23 Buoy Position 52° 50'.225'N 000° 21'.758'E.

This notice cancels NtM 02/ 2025.

28.02.25.

P.J.Jary.

Harbour Master.

King's Lynn,

Norfolk PE30 ILL

www.kingslynnport.co.uk