
Spoil Ground Area
Issue Date: 18th July 2024
Date of Survey: 17th July 2024
52°50'.80N
00° 21'.00 E
00° 21'.80 E
00° 22'.20 E
52° 50'.40 N
00° 22'.40 E
52° 50'.00 N
52° 49'.60 N
"S" Buoy
NW By Fl.Y 5s
Tango buoy
No.22 Buoy
No.21 Buoy
No.23 Buoy
No.24 Buoy
Outline of Disposal area.
1m above Dock sill
Dock sill
Approx Eastern Limit of spoil ground
West Stones Bcn
Z Bcn
PORT of KING'S LYNN
DATUM:
Chart Datum Hunstanton
(Dock Sill)
Every endeavour is made to ensure the accuracy of the information given at the time of the the survey, but King's Lynn Conservancy Board cannot accept any liability whatsoever for the consequences of any inaccuarcies shown, however caused.
The information given on this drawing is only valid for the day of the survey
Depths in Metres:
Where underlined, then above dock sill